

TOLLWAY LOCATING PROCEDURES

Pre-mark (White Line) the location in the field.



Prepare a sketch or plan sheet of the area showing the approximate location.

Request an Illinois Tollway locate at www.illinoisvirtualltolway.com/utilitylocates

Follow the directions on the form.

The marked area (The Tolerance Zone) is defined as a strip of land at least 4 feet wide, but not wider than the width of the underground facilities, plus 24" on each side.

The tolerance zone is the approximate location of the underground facilities. Excavation within the tolerance zone requires extra care and precaution. The Contractor must hand dig and expose (pothole) 360 degrees the Tollway facilities that are within the tolerance zone.



A SKETCH OR PLAN SHEET SHOWING LOCATION MUST BE INCLUDED WITH THE LOCATE REQUEST

Unless contacted, the Contractor can proceed with the work after the 48-hour period. The Tollway facilities are marked within 48 hours/two (2) business days and are valid for 28 days.

The Tollway locates apply only to Tollway facilities. Contact J.U.L.I.E. to locate other utilities. Utility owners that don't participate in the J.U.L.I.E. system must be contacted directly.

Contact: Tollway Utility / Permit Section
Phone: (630) 241-6800 Ext. 3306
Fax: (630) 271-7568
Email: pmathez@getipass.com